

**Final Meeting Minutes  
Restoration Advisory Board (RAB) Meeting  
Sunflower Army Ammunition Plant  
Wednesday, July 6 2005**

**1) Introductions.**

The RAB meeting was held in the Clearview City Ball Room. Mr. Tony Spaar, Commander's Representative at Sunflower Army Ammunition Plant (SFAAP), called the meeting to order at approximately 6:00 P.M.

**2) Review and Approve Minutes from May 4, 2005 meeting.**

Minutes from the May 4, 2005 meeting were available for Board review. A motion was made and seconded to accept the minutes as written. The RAB voted to accept the minutes as written.

**3) Installation Restoration Program (IRP) Project update.**

A. *Corps of Engineers' Update.* Since the May 4, 2005 RAB, the Army Corps of Engineers has been performing technical reviews of Shaw's Remedial Investigation Reports and Corrective Measures Report. Remedial Investigative Reports reviewed include Solid Waste Management Units (SWMU) 60 and 61 and two Areas of Concern (AOC) 3 and 13. USACE also reviewed the Phase I Groundwater Operable Unit No. 1 Report. Corrective Measures Reports reviewed include SWMUs 10 and 22. These include both draft and draft final reports. USACE also finishing up the CERCLA Five Year Review (where some contamination was left in place). This report is currently being reviewed by the Corps' internal technical review team.

B. *Shaw Update of Ongoing Work.* All field work has been completed. Currently working towards finalizing reports documenting previous field activities. Draft investigative reports yet to be submitted include SWMUs 18 (Old and New Sanitary Landfills), 25 (Nitrocellulose Area Ditches), 41 (Calcium Carbonate Cake Landfill), 53 (Burn and Debris Area) and 66 (Stream Study). Draft Corrective Measures Report yet to be submitted include SWMU 60.

**4) New Business.**

Discussed transfer of SFAAP to SRL.

**6) IRP Questions or Comments from Public.**

**7) Next Meeting Date & Proposed Agenda Items**

Next meeting: *September 7, 2005*

A bus trip is planned during the next RAB to tour SFAAP. Meet at the gate by 5:30.

**8) Adjourn RAB**